



## APC LATE MODEL SERIES Memo

### **APC Late Model Series Teams: APC Series Engine Repair Facilities:**

APC Late Model Series maintains a zero-tolerance policy of inspection and conformability to all guidelines as specified by the manufacturer regarding our crate engine program.

ALL engine specifications MUST be within the specifications as outlined in the GM 604/602 crate engine manual & Ford 347SR/SR7 crate engine manual.

APC Late Model Series will continue to use any means necessary to inspect, test & verify that ALL engine components are within the specifications outlined in the GM 604/602 crate engine manual & Ford 347SR/SR7 crate engine manual

If you have questions or concerns please contact APC Late Model Series Race/Tech Director – Darryl Timmermans – [dtimmermans38@hotmail.com](mailto:dtimmermans38@hotmail.com) or 519-872-0666.

**APC LATE MODEL SERIES  
RACE/TECH DIRECTOR  
DARRYL TIMMERMANS**